ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

# BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 10 | Dodda Bommasandra |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0001, W0004, W0007, W0022, W0025, W0014, W0105 | NA | BEL 2nd block |
| **Segment No.** | **Total Length (m)** | |
| 10/C-W0001/S065605 | 497.09 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 181.35 | 77.555926 | 13.067671 | 77.556372 | 13.069251 | Bel 2nd Block | 1st main road |
| 2 | 157.87 | 77.555399 | 13.067725 | 77.556831 | 13.067469 | BEL 2nd Block | 3rd main road |
| 3 | 157.87 | 77.555399 | 13.067725 | 77.556831 | 13.067469 | BEL 2nd Block | 4th cross road |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drains and drains at BEL 2nd Block in ward no. 10 Vidyaranyapura sub division | 4000000 | 2015-16 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2015 - 2016 | Asphalting | |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Asphalting work | 010-16-000002 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| BBMP/EE/BTP/WO/19/2017-18 | 07/04/2017 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 28/04/2017 | 28/04/2018 | No |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| K. Anilkumar | | 0.00 |
| **Phone No.** | **E-Mail ID** | |
| 9845818296 | | |

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 2 | | madavrao |
| **Date of Inspection** | **Remarks** | |
| 08/06/2017 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |
| Segment Start | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | Parameshwaraiah | 09/06/2017 | 08/07/2017 | Approved |
| SE | K.M.Vasu | 08/06/2017 | 08/07/2017 | Verified |
| EE | Mohandas | 08/06/2017 | 08/07/2017 | Verified |
| AEE | Shivakumar m goudar | 08/06/2017 | 08/07/2017 | Verified |

| | | | | |
|---|---|---|---|---|
| AE | Madhavarao | 08/06/2017 | 08/07/2017 | Mobile verification done |
| AE | Madhavarao | 08/06/2017 | 08/07/2017 | Forwarded |